



AR10 mag Release



USE A .312 cutter -

when on location go down .930 - back up to .720 then make table movement of .100 in both directions. Dial over on the X movement .002 to clean the walls up.

.097-.099 to depth shown

